

## After service information for existing controller accessory

Existing HYROP control panel (2  $\mu$ -com type and 3  $\mu$ -com type) is already manufacturing discontinuance, and a new spare parts supply is a situation that cannot possible. After service information on each part is shown as follows.

CONTROLLER	ACCESSARY	TYPE	MAKER	After service information	Repair recommend equipment
3 $\mu$ -com HYROP CONTROL PANEL	Control unit	CTU-02	Meisei Electric	Repair Possible. But it depends on the possession part stock. (Repair time limit:2015)	MH-PC4
	Serial transmission unit	SIU-03	Meisei Electric	Repair Possible. But it depends on the possession part stock. (Repair time limit:2015)	MH-PC4
	Sequencer	SYSMAC	OMRON	Repair Possible. (Correspondence time limit depends on the manufacturer policy. )	MELSEC
	Maintenance PC	—	—	After service ended	Existing PC
2 $\mu$ -com HYROP CONTROL PANEL	Control unit	VME board	Fuji Electronics	After service ended	MH-PC4
	Sequencer	SYSMAC	OMRON	Repair Possible. (Correspondence time limit depends on the manufacturer policy. )	MELSEC
	Maintenance PC	—	—	After service ended	Existing PC

Note) Above-mentioned after service information is possible situation at the time of February, 2009, and acknowledge the possibility of changing by the manufacturing situations of parts and restricting the quantity of inventory in the future, please.