

## After service information for existing controller accessory

Existing controller (MPC-16A, MPC-32A) is already manufacturing discontinuance, and a new spare parts supply is a situation that cannot be possible. After service information on each part is shown as follows.

CONTROLLER	ACCESSARY	MAKER	After service information	Repair recommend equipment
MPC-16A	MELSEC-A	Mitsubishi Electric	Repair Possible (Correspondence time limit depends on the manufacturer policy. )	MHPC-M
	CPU Board I/O Board	MH	After service ended	
	Monitor equipment (FC-9801)	NEC	After service ended	
MPC-32A	HDC500 ICS2500	Fuji Electric	Repair possible (Correspondence time limit depends on the manufacturer policy. )	MHPC-M
	Program loader FM-R	Fuji Electric	After service ended	
	CPU Board I/O Board	MH	Repair possible. But it is when it is not possible to repair by the breakdown situation. (Repair time limit: 2016)	
	Monitor equipment (FC-9801)	NEC	After service ended	
	Image processing unit IP-1	MHI	After service ended	
	CCD Camera	TOSIBA SONY	Repair possible (Correspondence time limit depends on the manufacturer policy. )	
INDUCTOSYN PANEL	Each board	MHI	After service ended	MP-SCALE UNIT PANEL

Note) Above-mentioned after service information is possible situation at the time of February, 2009, and acknowledge the possibility of changing by the manufacturing situations of parts and restricting the quantity of inventory in the future, please.