

HYROP制御盤 製造中止リスト

<HYROP(04E)>

No.	ITEM	TYPE	SUPPY	SUPPLY TIME LIMIT	REPAIR	REPAIR TIME LIMIT	REMARKS
1	CPU UNIT	HSC-4000	Inpossible	-	Inpossible	-	
2	CPU BOARD/B.P.U	LCP001A	Inpossible	-	Inpossible	-	
3	CPU BOARD/E.P.U	LCP010A	Inpossible	-	Inpossible	-	
4	CPU BOARD/P.I.F	LCP088A	Inpossible	-	Inpossible	-	
5	CPU BOARD/B.C	LCP090A	Inpossible	-	Inpossible	-	
6	CPU BOARD/MEM.	LMM020A	Inpossible	-	Inpossible	-	
7	CPU BOARD/C.T.M	LMM008A	Inpossible	-	Inpossible	-	
8	CPU BOARD/PRG	LIO000A	Inpossible	-	Inpossible	-	
9	PIO BOARD/DIO	HLT275A	Inpossible	-	Possible	2009/12	
10	PIO BOARD/RI/OW	LLG020A	Inpossible	-	Inpossible	-	
11	PIO BOARD/CNT	LPT030A	Inpossible	-	Possible	2009/12	
12	PIO BOARD/AI	LPA008A	Inpossible	-	Possible	2012/3	
13	PIO BOARD/AO	LPA120A	Inpossible	-	Possible	2009/12	
14	PIO BOARD/AO	LPA100A	Possible	No time limit now	Possible	No time limit now	Break down item
15	A-PACK BOARD/OPE.AMP	AOA-01	Inpossible	-	Possible	2011/3	
16	A-PACK BOARD/OPE.AMP	AOA-03B	Inpossible	-	Inpossible	-	
17	A-PACK BOARD/OPE.AMP	AOA090A	Inpossible	-	Possible	2011/3	
18	A-PACK BOARD/INPECANCE PACK	AIP-02	Inpossible	-	Possible	2011/3	
19	A-PACK BOARD/INPECANCE PACK	AIP-06	Inpossible	-	Possible	2011/3	
20	A-PACK BOARD/MULTI-PLTER	ASE091A	Inpossible	-	Inpossible	-	
21	A-PACK基板/MICRO REED RELAY	MRY-21A	Inpossible	-	Possible	2011/3	

<04M/D>

No.	ITEM	TYPE	SUPPLY	SUPPLY TIME LIMIT	REPAIR	REPAIR TIME LIMIT	REMARKS
1	CPU BOARD/D-BPU-1	LCP100A	Inpossible	-	Inpossible	-	
2	CPU BOARD/D-BPU-2	LCP110A	Inpossible	-	Inpossible	-	
3	CPU BOARD/P-MEM	LMM100A	Inpossible	-	Inpossible	-	
4	CPU BOARD/D-MEM	LMM120A	Inpossible	-	Inpossible	-	
5	CPU BOARD/D-PIF	LCP170A	Inpossible	-	Inpossible	-	
6	CPU BOARD/PI/O-CE	LCE230A	Inpossible	-	Inpossible	-	
7	CPU BOARD/PADT-CE	LIO200A	Inpossible	-	Inpossible	-	
8	CPU BOARD/PADT-CE	LIO210A	Inpossible	-	Inpossible	-	
9	PIO BOARD/UD	LUD001A	Inpossible	-	Inpossible	-	
10	PIO BOARD/AI	LPA008A	Inpossible	-	Possible	2012/3	
11	PIO BOARD/AO	LPA100A	Possible	No time limit now	Possible	No time limit now	Break down item
12	PIO BOARD/CNT	LPT030A	Inpossible	-	Possible	2009/12	
13	PIO BOARD/AO	LPA120A	Inpossible	-	Possible	2009/12	
14	PIO BOARD/RI/OW	LLG020A	Inpossible	-	Inpossible	-	
15	PIO BOARD/RIW	LLG040A	Inpossible	-	Possible	2012/3	
16	PIO BOARD/OPT ROW	LLG100A	Inpossible	-	Possible	2012/3	
17	PIO BOARD/OPT ROW	LLG110A	Inpossible	-	Possible	2012/3	
18	PIO BOARD/DI	LPD000A	Inpossible	-	Possible	2012/3	
19	PIO BOARD/DO	LPD110A	Inpossible	-	Inpossible	-	
20	A-PACK BOARD/OPE.AMP	AOA-01	Inpossible	-	Possible	2011/3	
21	A-PACK BOARD/OPE.AMP	AOA-03B	Inpossible	-	Inpossible	-	
22	A-PACK BOARD/OPE.AMP	AOA090A	Inpossible	-	Possible	2011/3	
23	A-PACK BOARD/IMP PI	AIP-02	Inpossible	-	Possible	2011/3	
24	A-PACK BOARD/IMP PI	AIP-06	Inpossible	-	Possible	2011/3	
25	A-PACK BOARD/	ASE091A	Inpossible	-	Inpossible	-	
26	A-PACK BOARD/	AFA060A	Inpossible	-	Inpossible	-	
27	A-PACK BOARD/RYP I	MRY-21A	Inpossible	-	Possible	2011/3	

<R600>

No.	ITEM	TYPE	SUPPY	SUPPLY TIME LIMIT	REPAIR	REPAIR TIME LIMIT	REMARKS
1	R600 UNIT	HSC4500	Inpossible	-	Possible	2016/9	
2	R600 PS	LPE001	Inpossible	-	Possible	2016/9	
3	R600 CPU	LPU004	Inpossible	-	Possible	2016/9	
4	R600 HPU	LPU014	Inpossible	-	Possible	2016/9	
5	R600 NCP	LNC000	Inpossible	-	Possible	2016/9	
6	R600 DIF	LFI000	Inpossible	-	Possible	2016/9	
7	R600 RIF-D	LFI140	Inpossible	-	Possible	2016/9	
8	R600 PIFA	LSU010	Inpossible	-	Possible	2016/9	
10	R600 PIF-CON	HSC6800	Possible	No time limit now	Possible	No time limit now	
12	PI/O DI	LPD200A	Inpossible	-	Possible	2012/3	
13	PI/O DO	LPD300A	Inpossible	-	Possible	2012/3	
14	PI/O AI	LPA008A	Inpossible	-	Possible	2012/3	
15	PI/O AO	LPA100A	Possible	No time limit now	Possible	No time limit now	Break down item
16	PI/O CNT	HCN000A,B	Possible	No time limit now	Possible	No time limit now	
17	PI/O UD	LUD070A	Inpossible	-	Possible	2012/3	